

Alarm temperature meter AT-10



1. Indoor and outdoor over temperature alarm sounds 6 times every minute when measuring temperature exceeds setting temperature point.
2. Show and set current indoor and outdoor temperature
3. Show Max/Min temperature.
4. Stand for shelf or hanging hole at back side.

Main functions and parameters:

Measuring temperature range	-50°C~70°C(-58°F~158°F)
Display resolution	0.1°C(0.2°F)
Accuracy	±1°C
Selectable temperature unit	°C or °F
Sampling period	30sec
LCD size	42.5*35.2mm
Product size	110*70*20mm
Weight	80g(Excluding the battery)

