

## Digital thermo-hygrometer BTH-4



Large LCD display shows current temperature/humidity.

1. Measure and display the indoor/outdoor temperature and indoor/outdoor humidity.
2. Automatically memorize the Max./Min. values of the indoor/outdoor temperature and indoor humidity.
3. Switch between °C / °F.
4. Recovery functions on the Max./Min. Values.
5. Stand for shelf or hanging hole at back side.

### Main parameters:

Measuring temperature range	-50°C~+70°C(-58°F~158°F)
Measuring humidity range	10%RH~95%RH
Accuracy	±1°C (or±2°F), ±5% RH
Resolution	0.1°C (0.1°F) &1%RH
Selectable temperature unit	°C or °F