

## Digital thermo-hygrometer TH-38



### Indoor and Outdoor Temperature and Hygrometer

1. With °C / °F button to convert Celsius and Fahrenheit
2. Can be hung on the wall or on the table, the back has a hook and bracket.
3. 1.5v AAA battery External 1.5 m water temperature sensor.
4. Applicable for factories, warehouses, building air-conditioning management, hospitals, types

of aquaculture, room, office, hotel, laboratory, of modern energy conservation is a good helper.

#### Main parameters:

|                     |                         |
|---------------------|-------------------------|
| Outdoor temperature | -40°C~+70°C -40°F~158°F |
| Indoor temperature  | 0°C~+50°C 32°F~122°F    |
| Accuracy            | ±1°C ±5%RH              |
| Resolution          | 0.1°C(0.1°F)            |
| Humidity            | 10% ~ 99% ± 5%          |
| Power supply        | One 1.5volt AAA battery |

